

Technical Information

Index December 1992

Note: Please replace your index with this updated version. This is the final index for the 1992 notebook

Topic	Title	Section	Page
A			
Accuracy	Large Format Output Devices	Miscellaneous	1
Acronyms	Acronyms	Miscellaneous	1-4
Common link acronyms	PostScript to High-End Links	Miscellaneous	4
Additive color primaries (RGB)	Color in Printing	Color	2
	Color Spaces and PostScript Level 2	Color	1-2
Addressability	Addressability and Spot Size	Miscellaneous	1-2
	Hard Dot, Soft Dot	Halftoning	2
	Line Art	Scanning	2
	Resolution and Screen Ruling	Halftoning	2
Adobe Type Manager (ATM)	PostScript Font Basics	Fonts	2-3
	Understanding PostScript Fonts	Fonts	1
AFM file (see Font metrics)			
Analog and digital	The Scanning Process	Scanning	1-2
Application Specific Integrated Circuit (ASIC)	Color Management	Color	4
Argon ion laser (see Lasers)			
Association Typographique International (ATypI)	Fonts and Font Licenses	Fonts	2
Automatic calibration	Automatic Calibration	Calibration	1-2
Automatic image analysis	Color Management	Color	4
Automatic Page Positioning (APP)	Large Format Output Devices	Miscellaneous	3-4
B			
Bézier curve	PostScript Font Basics	Fonts	2
Bit	Scanned File Size	Scanning	1-2
Bitmapped (see Raster images)			
Bitmapped font (see Font)			
Blend	Blends and Shadestepping	Halftoning	1-4
	Blend Update	Halftoning	1-4
Blends versus scans	Blend Update	Halftoning	1
Duplication, sampled data, and synthetic data blends	Blend Update	Halftoning	1
Maximum length of blend chart	Blends and Shadestepping	Halftoning	4
Mysterious blend problems	Blend Update	Halftoning	3
Byte	Scanned File Size	Scanning	1-2
C			
Cache (see Font cache and Screen cache)			
Calibration	Calibration	Calibration	1-4
	Color Spaces and PostScript Level 2	Color	4
	Density and Dot Percent	Calibration	4
Automatic calibration	Automatic Calibration	Calibration	1-2
On imagesetter paper	Calibrating on Imagesetter Paper	Calibration	1-4
Scanner	The Scanning Process	Scanning	2
Through color rendering dictionaries	The Scanning Process	Scanning	4
Capstan	Large Format Output Devices	Miscellaneous	1-3

Topic	Title	Section	Page
Cause & effect diagram.....	Basic Statistical Process Control	Miscellaneous	1-2,3
CCMac	PostScript to High-End Links	Miscellaneous	2,3,4,6
Centigrade to fahrenheit conversion	Converting Measurements	Miscellaneous	2
Charts			
Additive color primaries and their mixtures	Color in Printing	Color	2
Addressability and overlap of spot size	Addressability and Spot Size.....	Miscellaneous	2
Blend file size chart.....	Blend Update.....	Halftoning.....	2
Check sheet for imagesetter film defects	Basic Statistical Process Control	Miscellaneous	3
Communications ports.....	Troubleshooting PostScript Errors	Miscellaneous	3
Common link acronyms	PostScript to High-End Links	Miscellaneous	4
Density setting versus dmax.....	Calibration	Calibration.....	3
Dmax value versus light transmitted.....	Graphic Arts Film Materials	Film & Processing	3
Dot % on imagesetter paper	Calibrating on Imagesetter Paper	Calibration.....	3
File storage methods	PostScript to High-End Links	Miscellaneous	4
Film quality checklist.....	Analyzing Film Output.....	Film & Processing	1
Functions performed by a color computer	The Scanning Process.....	Scanning	1
Hazardous materials identification system	Film Processor Chemicals.....	Film & Processing	1
Image file size	Scanned File Size	Scanning	4-5
Imagesetter/RIP background information.....	Troubleshooting PostScript Errors	Miscellaneous	1
Job Complexity.....	Outputting PostScript Jobs	Miscellaneous	4
Maximum length of blend chart.....	Blends and Shadestepping	Halftoning.....	4
Measurement conversions.....	Converting Measurements	Miscellaneous	1-2
Offending PostScript commands	Troubleshooting PostScript Errors	Miscellaneous	4
Output check list	Outputting PostScript Jobs	Miscellaneous	4
Rational tangent screening charts	Rational and Irrational.....	Halftoning.....	2
Recommended levels of gray	Resolution and Screen Ruling	Halftoning.....	3
Regulation and enforcement agencies	Film Processor Chemicals	Film & Processing	2
Requested versus measured dot percent.....	Calibration	Calibration.....	2
Resolution settings in mm., cm., and in.....	Calibration	Calibration.....	2
RIP/recorder errors	Troubleshooting PostScript Errors	Miscellaneous	2
RIP status.....	Troubleshooting PostScript Errors	Miscellaneous	2
Selected output device specifications.....	Large Format Output Devices	Miscellaneous	1
Time chart for imagesetter film dmax	Basic Statistical Process Control	Miscellaneous	4
Troubleshooting common film processor problems	Maintaining a Film Processor	Film and Processing	4
System 7 capability.....	System 7	Miscellaneous	3
System 7 printer drivers.....	System 7	Miscellaneous	4
Characteristic curve	Graphic Arts Film Materials	Film & Processing	2
Characterization.....	Color Spaces and PostScript Level 2	Color	4
Chemical waste disposal	Film Processor Chemicals	Film & Processing	2-3
Chokes and Spreads.....	Trapping	Color	1
Chroma	Color Management	Color	4
ChromaCom	PostScript to High-End Links	Miscellaneous	2,4,6
CIE L*a*b* (see Commission International de l'Eclairage)			
Clip art.....	Line Art	Scanning	4
Closed systems	Color Management	Color	1
CMYK (see Process colors)			
Color Assistant	Color Management	Color	4
Color			
Color computer	The Scanning Process	Scanning	1-3
Color gamut	Color Spaces and PostScript Level 2	Color	3
Color separation	Color in Printing	Color	3
Color separation in flexography	PostScript and Flexography	Miscellaneous	4
Color shifts	Moiré	Color	2
Color spaces	Moiré, Rosettes, and Color Shifts.....	Color	2-3
Color management	Color Spaces and PostScript Level 2	Color	1-4
Device dependent output	Color Management	Color	1-2
Input device calibration.....	Color Management	Color	1
Monitor calibration	Color Management	Color	1-2
Color Path	PostScript to High-End Links	Miscellaneous	3,6
Commission International de l'Eclairage (CIE)	Color Spaces and PostScript Level 2	Color	2-3
Communications ports	Troubleshooting PostScript Errors	Miscellaneous	3
Communication errors.....	Troubleshooting PostScript Errors	Miscellaneous	5

Topic	Title	Section	Page
Compression	Scanned File Size	Scanning	4
Concert 2.0	Understanding PostScript Fonts	Fonts	5
Contacting	Graphic Arts Film Materials	Film & Processing	4
Contrast	Graphic Arts Film Materials	Film & Processing	1-3
Control strips	Maintaining a Film Processor	Film & Processing	3
Converting measurements	Converting Measurements	Miscellaneous	1-2
Cora	Acronyms	Miscellaneous	1
Custom font program	Line Art	Scanning	4
Cutoff	Large Format Output Devices	Miscellaneous	3

D

Decimal to fraction conversion	Converting Measurements	Miscellaneous	2
Degradé (see Blend)			
Densitometer	Calibration	Calibration	4
	Calibrating on Imagesetter Paper	Calibration	2
Density	Analyzing Film Output	Film & Processing	3
	Calibration	Calibration	1
	Calibrating on Imagesetter Paper	Calibration	2
	Density and Dot Percent	Calibration	1-4
Density setting (see Laser intensity)			
DENSY	Acronyms	Miscellaneous	2
Device dependence in halftoning	Rational and Irrational	Halftoning	4
Device independence	Line Art	Scanning	2
Device independent color	Color Spaces and PostScript Level 2	Color	1
Device specific versus device independent	Outputting PostScript Jobs	Miscellaneous	1
Disk storage	Understanding PostScript Fonts	Fonts	2
Dmax	Analyzing Film Output	Film & Processing	1-4
	Calibrating on Imagesetter Paper	Calibration	2
	Graphic Arts Film Materials	Film & Processing	1-3
Dot (see Halftone dot)			
Dot percent	Resolution and Screen Ruling	Halftoning	1
On film	Analyzing Film Output	Film & Processing	3-4
	Automatic Calibration	Calibration	1-2
	Density and Dot Percent	Calibration	1-4
	Hard Dot, Soft Dot	Halftoning	2
	Graphic Arts Film Materials	Film & Processing	4
Dots per inch	Hard Dot, Soft Dot	Halftoning	2
Draw (see Vector images)			
Double duplo mode	Large Format Output Devices	Miscellaneous	3
Drum	Large Format Output Devices	Miscellaneous	1-3
Duping	Graphic Arts Film Materials	Film & Processing	4
Duplo mode	Large Format Output Devices	Miscellaneous	3

E

Edge sharpness	Graphic Arts Film Materials	Film & Processing	3-4
Electronic technology quiz	Technology Quiz	Miscellaneous	1
Elliptical halftone dot shape	Digital Halftone Dots	Halftoning	3
	Halftone Dot Shape	Halftoning	2
Encryption of fonts	PostScript Font Basics	Fonts	3-4
Enlargement of scanned images	Scanned File Size	Scanning	3
	From Input to Output	Scanning	3
Emulsion (see Film)			
EPS files	Scanned File Size	Scanning	1
Extension	PostScript to High-End Links	Miscellaneous	1
External drum	Large Format Output Devices	Miscellaneous	1-2

Topic	Title	Section	Page
F			
Fahrenheit to centigrade conversion	Converting Measurements	Miscellaneous2
File formats.....	PostScript to High-End Links	Miscellaneous4
File size charts for line art, grayscale, and color	Scanned File Size	Scanning5
File storage.....	PostScript to High-End Links	Miscellaneous5
Fill	Trapping.....	Color2
Film			
Base	Analyzing Film Output.....	Film & Processing2
Contacting	Graphic Arts Film Materials	Film & Processing4
Contrast	Graphic Arts Film Materials	Film & Processing2
Dmax.....	Graphic Arts Film Materials	Film & Processing3
Effect of laser on	Lasers and Films.....	Film & Processing1-2
Emulsion	Analyzing Film Output.....	Film & Processing2
Exposure	Maintaining a Film Processor	Film & Processing1
Film resolution.....	Graphic Arts Film Materials	Film & Processing2
Film storage	Maintaining a Film Processor	Film & Processing1
Film types (lith, rapid access, and hybrid)	Graphic Arts Film Materials	Film & Processing1
Latent image	Maintaining a Film Processor	Film & Processing2
Linearity.....	Graphic Arts Film Materials	Film & Processing1
On-line processing.....	Maintaining a Film Processor	Film & Processing4
Output.....	Analyzing Film Output.....	Film & Processing1-4
Oxidation.....	Maintaining a Film Processor	Film & Processing3
Processor chemicals.....	Film Processor Chemicals.....	Film & Processing1-4
Registration.....	Analyzing Film Output.....	Film & Processing2
Right/wrong reading	Large Format Output Devices	Miscellaneous3
	Analyzing Film Output.....	Film & Processing1-2
Film Processing			
Cleaning a film processor	Maintaining a Film Processor	Film & Processing3
Developer, stop bath, fixer, and wash	Maintaining a Film Processor	Film & Processing2
Effect of agitation, time, and temperature	Maintaining a Film Processor	Film & Processing2
Effect on halftone dot percent	Calibration	Calibration1
	Density and Dot Percent.....	Calibration2
	Maintaining a Film Processor	Film & Processing3-4
Filter (see Raster Image Processor)			
Final page calculations.....	PostScript to High-End Links	Miscellaneous2
Flatness.....	Outputting PostScript Jobs	Miscellaneous4
Flexography	PostScript and Flexography	Miscellaneous1-6
Color separation in.....	PostScript and Flexography	Miscellaneous4
Dot gain in	PostScript and Flexography	Miscellaneous4
Distortion in	PostScript and Flexography	Miscellaneous1,2,5,6
Halftone dot shape in	PostScript and Flexography	Miscellaneous3,6
Screen ruling in	PostScript and Flexography	Miscellaneous3
Trapping in	PostScript and Flexography	Miscellaneous3
Font	PostScript Font Basics	Fonts1-4
Bitmapped font	PostScript Font Basics	Fonts2
	Understanding PostScript Fonts	Fonts1,3,4
Downloading	Understanding PostScript Fonts	Fonts4
Encryption	PostScript Font Basics	Fonts3-4
Hints	PostScript Font Basics	Fonts3
Outline font	PostScript Font Basics	Fonts2
	Understanding PostScript Fonts	Fonts1,3,4
Printer font	PostScript Font Basics	Fonts2
Screen font.....	PostScript Font Basics	Fonts2
Storage	Understanding PostScript Fonts	Fonts3
Suitcase	PostScript Font Basics	Fonts2
Type 1 versus Type 3.....	PostScript Font Basics	Fonts3-4
Font cache	Understanding PostScript Fonts	Fonts2
Font ID issues.....	Understanding PostScript Fonts	Fonts4
Font licenses	Fonts and Font Licenses	Fonts1-2
Font metrics.....	PostScript Font Basics	Fonts4
Font misuse	Fonts and Font Licenses	Fonts2

Topic	Title	Section	Page
Format size	Large Format Output Devices	Miscellaneous	1,3
Formulas			
Blend factor	Blends and Shadestepping	Halftoning	2
Dot area	Calibrating on Imagesetter Paper	Calibration	4
File size	Scanned File Size	Scanning	6
Grays	Blends and Shadestepping	Halftoning	2
Grays available	Blends and Shadestepping	Halftoning	2
Fountain (see Blend)			
Fraction to decimal conversion	Converting Measurements	Miscellaneous	2
Fringe	Graphic Arts Film Materials	Film & Processing	3-4
	Hard Dot, Soft Dot	Halftoning	1-2

G

Gamma	Graphic Arts Film Materials	Film & Processing	3
GCR (Gray Component Replacement)	Color in Printing	Color	4
Gigabyte	Scanned File Size	Scanning	2
Gradation (see Blend)			
Graduated tint (see Blend)			
Graphic arts film materials	Graphic Arts Film Materials	Film & Processing	1-4
Graphic arts lasers	Lasers and Films	Film & Processing	2
Grays	Resolution and Screen Ruling	Halftoning	2-4
Gray levels, compression of	Calibration	Calibration	2
In blends	Blends and Shadestepping	Halftoning	2
In screen angle and ruling chart	Angle and Ruling Recommendations	Screen Angle & Ruling	2-5
	Part II: Angle and Ruling Recommendations	Screen Angle & Ruling	2-4
Recommended levels of (chart)	Resolution and Screen Ruling	Halftoning	3

H

Halftone cell	Measuring Screen Angle and Ruling	Screen Angle & Ruling	1
	Digital Halftone Dots	Halftoning	1
	Rational and Irrational	Halftoning	2
Halftone dot, digital	Digital Halftone Dots	Halftoning	1-4
	Hard Dot, Soft Dot	Halftoning	1-2
Halftone dot percentages	Color in Printing	Color	3
	Calibration	Calibration	1
Halftone dot shape	Blends and Shadestepping	Halftoning	3
	Digital Halftone Dots	Halftoning	2-4
	From Input to Output	Scanning	1-4
	Halftone Dot Shape	Halftoning	1-4
	PostScript and Flexography	Miscellaneous	3,6
Halftone dot shape in flexography	Resolution and Screen Ruling	Halftoning	1
Halftoning	Hard Dot, Soft Dot	Halftoning	1-2
	Outputting PostScript Jobs	Miscellaneous	1-2
	Rational and Irrational	Halftoning	1-4
	Moiré, Rosettes, and Color Shifts	Color	1-3
Hard dot	Hard Dot, Soft Dot	Halftoning	1-2
	Lasers and Films	Film & Processing	2
Helium neon laser (see Lasers)			
Hell, Dr. Rudolf, -Ing.	Graphic Arts Film Materials	Film & Processing	2
High-end links	PostScript to High-End Links	Miscellaneous	1-6
Hints (i.e., font hints)	PostScript Font Basics	Fonts	3
HQS Screening	Angle and Ruling Recommendations	Screen Angle & Ruling	1
	Measuring Screen Angle and Ruling	Screen Angle & Ruling	1,2
	Moiré	Color	4
	Part II: Angle and Ruling Recommendations	Screen Angle & Ruling	1
	Rational and Irrational	Halftoning	3
Hue	Color Management	Color	4
Hybrid film	Graphic Arts Film Materials	Film & Processing	1

Topic	Title	Section	Page
I			
Image replacement	PostScript to High-End Links	Miscellaneous4
Imagesetter.....	Troubleshooting PostScript Errors	Miscellaneous1
Imagesetter paper.....	Calibrating on Imagesetter Paper	Calibration	1-4
Imposed layout.....	Large Format Output Devices	Miscellaneous1
Interface.....	PostScript to High-End Links	Miscellaneous1,2
Internal drum	Large Format Output Devices	Miscellaneous	1-2
Interpolation	Line Art	Scanning2
	The Scanning Process	Scanning4
Irrational tangent screening.....	Rational and Irrational.....	Halftoning1-4
I.S. Technology.....	Moiré, Rosettes, and Color Shifts.....	Color4
	Rational and Irrational.....	Halftoning1,4
K			
Kerning.....	PostScript Font Basics	Fonts4
Kilobyte	Scanned File Size	Scanning	1-2
Knockout.....	Trapping.....	Color2
L			
Large format output device.....	Large Format Output Devices	Miscellaneous	1-4
Laser diode (see Lasers)			
Laser intensity	Addressability and Spot Size.....	Miscellaneous	2-3
	Density and Dot Percent.....	Calibration	2-3
Lasers.....	Lasers and Films.....	Film & Processing	1-2
Laser spot	Addressability and Spot Size.....	Miscellaneous	1-2
	Hard Dot, Soft Dot	Halftoning	1-2
Latent image.....	Automatic Calibration	Calibration1
	Maintaining a Film Processor	Film & Processing1
LCH.....	Color Management	Color	3-4
Letterspacing	PostScript Font Basics	Fonts4
Levels of gray (see Grays)			
Lightness	Color Management	Color4
Linearity	Graphic Arts Film Materials	Film & Processing1
Linearization	Calibration	Calibration	1-2
	Density and Dot Percent	Calibration4
Line art (also see Vector images).....	From Input to Output	Scanning	2,4
	Line Art	Scanning	1-4
Line art versus halftones.....	Scanned File Size	Scanning3
Line ruling (see Screen ruling)			
Lines per inch	Hard Dot, Soft Dot	Halftoning2
Links	PostScript to High-End Links	Miscellaneous4
LinoColor 3.0	Color Management	Color2
Linotype Library	Fonts and Font Licenses	Fonts2
Linotype Utility			
Calibration	Calibration	Calibration	1-4
Halftone dot shape selection	Halftone Dot Shape	Halftoning3
Filter selections	Angle and Ruling Recommendations	Screen Angle & Ruling6
Outputting PostScript Jobs		Miscellaneous2
System 7 compatibility.....	System 7	Miscellaneous1
Lith film	Graphic Arts Film Materials	Film & Processing1
Logos	Line Art	Scanning4
M			
MacCTU	Color Management	Color3
Material data safety sheet (MSDS).....	Film Processor Chemicals	Film & Processing1

Topic	Title	Section	Page
Maximum density (see dmax)			
Measurement conversions.....	Converting Measurements	Miscellaneous.....	1-2
Megabyte	Scanned File Size	Scanning.....	1-2
Mergenthaler, Ottmar	Resolution and Screen Ruling	Halftoning.....	4
Micron (see Measurement conversions)			
Mid-tone jump	Digital Halftone Dots.....	Halftoning.....	3
	Halftone Dot Shape	Halftoning	2-3,4
Mil (see Measurement conversions)			
Moiré	Moiré.....	Color	1-4
	Moiré, Rosettes, and Color Shifts.....	Color	1-4
Checking on film	Analyzing Film Output.....	Film & Processing	3
Predicting.....	Moiré.....	Color	4
Moiré (sample)	What factors play a role in Moiré?.....	Color	1
Moiré period.....	Moiré, Rosettes, and Color Shifts.....	Color	4
Monitor calibration.....	Color Management	Color	2
Munsell Color Matching System.....	Color Management	Color	3
MSDS (see Material data safety sheet)			

N

Nanometer	Lasers and Films.....	Film & Processing	1
-----------------	-----------------------	-------------------------	---

O

Object-oriented (see Vector images)			
Offending commands (chart)	Troubleshooting PostScript Errors	Miscellaneous	4
Open systems.....	Color Management	Color	1
Operating system.....	System 7	Miscellaneous	1-4
	Understanding PostScript Fonts	Fonts	2
Optical jump (see Mid-tone jump)			
Outline font (see Font)			
Output check list	Outputting PostScript Jobs	Miscellaneous	4
Output time of scanned images	Scanned File Size	Scanning	4
	How do you keep scanned file size low...?	Scanning	1
	Outputting PostScript Jobs	Miscellaneous	3
Overprint	Trapping	Color	2

P

Paint (see Raster images)			
Pantone color (see Spot color)			
Pareto analysis	Basic Statistical Process Control	Miscellaneous	1,2
Pica (see Measurement conversions)			
Pict files	Scanned File Size	Scanning	1
Pixel.....	Scanned File Size	Scanning	3
Pixelization.....	Scanned File Size	Scanning	4
Plate-ready films	Analyzing Film Output.....	Film & Processing	1-2
Point (see Measurement conversions)			
PostScript			
Color in Level 2	Color Spaces and PostScript Level 2	Color	1-4
	The Scanning Process.....	Scanning	4
Errors	Troubleshooting PostScript Errors	Miscellaneous	1-6
File, creating.....	Troubleshooting PostScript Errors	Miscellaneous	4
	System 7	Miscellaneous	2
Fonts	PostScript Font Basics	Fonts	1-4
Grays in Level 2	Blend Update	Halftoning	4
Output	Outputting PostScript Jobs	Miscellaneous	1-4
Posterization.....	Blends and Shadestepping	Halftoning	1
Print Process Calibration (PPC)	Color Management	Color	3-4

Topic	Title	Section	Page
Print simulation on a monitor	Color Management	Color	2
Printer driver	System 7	Miscellaneous	4
	Understanding PostScript Fonts	Fonts	3
Printer description files	Outputting PostScript Jobs	Miscellaneous	1
Process calibration (see Calibration)			
Process color	Color in Printing	Color	1-4
Production Tools 1.0	Automatic Calibration	Calibration	1-2
	Large Format Output Devices	Miscellaneous	3-4
Proofing			
Checking for moiré and traps	Analyzing Film Output	Film & Processing	2-3
Types of proofs	Analyzing Film Output	Film & Processing	4

Q

Quadro mode	Large Format Output Devices	Miscellaneous	3-4
-------------------	-----------------------------------	---------------------	-----

R

Random Access Memory (RAM)	System 7	Miscellaneous	2
	Understanding PostScript Fonts	Fonts	2
Rapid access film	Graphic Arts Film Materials	Film & Processing	1
Raster Image Processor (RIP)	PostScript Font Basics	Fonts	3
	Understanding PostScript Fonts	Fonts	1-2
Errors	Troubleshooting PostScript Errors	Miscellaneous	2
Filter	Angle and Ruling Recommendations	Screen Angle & Ruling	1,6
Raster images	Line Art	Scanning	1-4
	Scanned File Size	Scanning	1-6
Rational tangent screening	Rational and Irrational	Halftoning	1-4
Read-Only Memory (ROM)	System 7	Miscellaneous	3
	Understanding PostScript Fonts	Fonts	2
Recorder	Troubleshooting PostScript Errors	Miscellaneous	1
Reduction of scanned images	Scanned File Size	Scanning	3
	From Input to Output	Scanning	3
Registration (see Film)			
Repeatability	Large Format Output Devices	Miscellaneous	1-3
Effect of environmental conditions on	Large Format Output Devices	Miscellaneous	3
Resin-coated paper (see Imagesetter paper)			
Resolution	Addressability and Spot Size	Miscellaneous	1-2
	Resolution and Screen Ruling	Halftoning	2-4
	From Input to Output	Scanning	1
Resolution independent (see Vector images)			
Resolution dependent (see Raster images)			
RGB (Red/Green/Blue, see Additive primaries)			
RGB to CMYK conversion	The Scanning Process	Scanning	2
RIFF files	Scanned File Size	Scanning	1
RIP (see Raster Image Processor)			
Rosette	Moiré	Color	1
	Moiré, Rosettes, and Color Shifts	Color	3
Rotary letter press	PostScript and Flexography	Miscellaneous	5
RS232 (see Communications ports)			
RT Screening	Angle and Ruling Recommendations	Screen Angle & Ruling	1
	Measuring Screen Angle and Ruling	Screen Angle & Ruling	1
	Moiré	Color	3
	Part II: Angle and Ruling Recommendations	Screen Angle & Ruling	1
	Rational and Irrational	Halftoning	1

Topic	Title	Section	Page
S			
Sample	Scanned File Size	Scanning	3
Scalable font (see Font)			
Scanning	The Scanning Process	Scanning	1-4
	From Input to Output	Scanning	3
Analyzing unit	The Scanning Process	Scanning	1-3
Color computer	The Scanning Process	Scanning	1-3
Electronic dot generator	The Scanning Process	Scanning	1-3
Exposure unit	The Scanning Process	Scanning	1-3
Scaling computer	The Scanning Process	Scanning	1-3
Scanning ratio	From Input to Output	Scanning	2
	How do you keep scanned file size low...?	Scanning	1
	Scanned File Size	Scanning	4
Scanned file size	Scanned File Size	Scanning	1-6
Scanned images (see Raster images)			
Scanner calibration	Color Management	Color	1
Scanner look-up tables	The Scanning Process	Scanning	4
Scanner resolution	From Input to Output	Scanning	1-4
	Line Art	Scanning	2-3
	Scanned File Size	Scanning	3-6
Screen angle	Resolution and Screen Ruling	Halftoning	2
Definition	Measuring Screen Angle and Ruling	Screen Angle & Ruling	1-2
In color printing	Moiré, Rosettes, and Color Shifts	Color	1-3
Measurement tool	Measuring Screen Angle and Ruling	Screen Angle & Ruling	3
On film	Analyzing Film Output	Film & Processing	4
Screen angle and ruling recommendations	Angle and Ruling Recommendations	Screen Angle & Ruling	1-6
	Moiré	Color	3
	Part II: Angle and Ruling Recommendations	Screen Angle & Ruling	1-4
Screen cache	Rational and Irrational	Halftoning	3
Screen ruling	Resolution and Screen Ruling	Halftoning	1
Choice of	Resolution and Screen Ruling	Halftoning	4
Definition	Measuring Screen Angle and Ruling	Screen Angle & Ruling	1-2
Importance in blends	Blends and Shadestepping	Halftoning	3
Measurement tool	Measuring Screen Angle and Ruling	Screen Angle & Ruling	3
On film	Analyzing Film Output	Film & Processing	4
On imagesetter paper	Calibrating on Imagesetter Paper	Calibration	1,4
Screen ruling in flexography	PostScript and Flexography	Miscellaneous	3
ScriptMaster II	PostScript to High-End Links	Miscellaneous	2,3,4,6
Silver halide	Maintaining a Film Processor	Film & Processing	3
Silver recovery	Film Processor Chemicals	Film & Processing	3
Slide scanner			
Resolution	Scanned File Size	Scanning	5
File size chart	Scanned File Size	Scanning	6
Soft dot	Hard Dot, Soft Dot	Halftoning	1-2
	Lasers and Films	Film & Processing	2
Spatial resolution	Scanned File Size	Scanning	2,3,4
	From Input to Output	Scanning	1
Spectral sensitivity of film	Graphic Arts Film Materials	Film & Processing	4
Spectrum of light	Lasers and Films	Film & Processing	1
Spot color	Color in Printing	Color	1,3
In blends	Blends and Shadestepping	Halftoning	4
Spot function	Digital Halftone Dots	Halftoning	4
Spot size (see Laser spot size)			
Spread	Trapping	Color	1
Specifications for Web Offset Printing (SWOP)	Color Management	Color	2
Statistical Process Control (SPC)	Basic Statistical Process Control	Miscellaneous	1-4
Stroke	Trapping	Color	2
Subtractive color primaries (CMYK)	Color in Printing	Color	2
	Color Spaces and PostScript Level 2	Color	1-2
Supercell	Rational and Irrational	Halftoning	3-4

Topic	Title	Section	Page
Survey	Linotype-Hell PostScript Survey.....	Miscellaneous	1-4
Synthetic art (see Vector images)			
System 7	System 7	Miscellaneous	1-4
Disk cache	System 7	Miscellaneous	3
Multitasking.....	System 7	Miscellaneous	2
Printer drivers.....	System 7	Miscellaneous	4
Publish and subscribe	System 7	Miscellaneous	2
Virtual memory.....	System 7	Miscellaneous	2
32 bit addressing	System 7	Miscellaneous	2
 T			
Technology quiz	Technology Quiz	Miscellaneous	1-4
Temperature conversions (°C to °F or vice versa)	Converting Measurements	Miscellaneous	2
TIFF files.....	Scanned File Size	Scanning	1
Time chart.....	Basic Statistical Process Control	Miscellaneous	1,3,4
Tonal range.....	Color Spaces and PostScript Level 2.....	Color	3
Tonal resolution	Scanned File Size	Scanning	2
	From Input to Output	Scanning	4
Total Quality Management (TQM)	Basic Statistical Process Control	Miscellaneous	4
Trademarks.....	Fonts and Font Licenses	Fonts	2
Transfer curve	Automatic Calibration	Calibration	2
	Calibration	Calibration	2
Trapping.....	Trapping	Color	1-6
Evaluating a trap on film	Analyzing Film Output.....	Film & Processing	2-3
Size of trap chart.....	Trapping	Color	4
Trapping in flexography	PostScript and Flexography	Miscellaneous	3
Two-color trapping sample.....	What factors are important in trapping?.....	Color	1
Troubleshooting			
Film Processor Problems.....	Maintaining a Film Processor	Film & Processing	3-4
PostScript Errors.....	Troubleshooting PostScript Errors	Miscellaneous	1-6
Typeface	PostScript Font Basics	Fonts	1
Typeface style.....	PostScript Font Basics	Fonts	1
Typeface family.....	PostScript Font Basics	Fonts	1
 U			
UCR (Under Color Removal).....	Color in Printing	Color	4
 V			
Variation.....	Basic Statistical Process Control	Miscellaneous	1
Vector font (See Font)			
Vector images	Scanned File Size	Scanning	1
Vignette (see Blend)			
Virtual memory	System 7	Miscellaneous	2
Virtual memory errors	Troubleshooting PostScript Errors	Miscellaneous	5
 W			
Wavelength	Lasers and Films.....	Film & Processing	1
WYSIWIG (What You See Is What You Get).....	Color Management	Color	2
	The Scanning Process	Scanning	2
 X			
XTract.....	PostScript to High-End Links	Miscellaneous	6